



*CONSTANT PRESSURE CLOSE: FOR CONSTANT PRESSURE CLOSE, REMOVE PURPLE WIRE FROM TERMINAL #5 AND CAP.

1- PHASE WIRING DIAGRAM
MSLHA-WW
REV. C DATE: 22.09.03

